
Allegro-Lite

Order of panel building

1) Tip panels

Spar cap carry—through segments are left jutting out of spar. Segments which are laminated are jigged to dihedral angle. Web hardwood insert takes the large crushing loads.



2) Mid panels

Spar cap carry—through inserts from compled tip are sandwiched into sparcap/core/rib assembly.

Prefabbed joiner—rod / ply—block unit is aligned with spar.

