

AG 03	Re $\nu$ CL = 20000	Ma $\nu$ CL = 0.000	Ncrit = 9.000
AG 03	Re $\nu$ CL = 30000	Ma $\nu$ CL = 0.000	Ncrit = 9.000
AG 03	Re $\nu$ CL = 40000	Ma $\nu$ CL = 0.000	Ncrit = 9.000
AG 03	Re $\nu$ CL = 60000	Ma $\nu$ CL = 0.000	Ncrit = 9.000
AG 03	Re $\nu$ CL = 100000	Ma $\nu$ CL = 0.000	Ncrit = 9.000

